Presious/Semi Precious (PALLADIUM LESS THAN 30%)

1 Turn on the power swich on your right side
2 Choose your course by (0 to 99)
1. <u>START TEMP</u> will Flash 2. <u>START TEMP</u> illuminates
3 Put the alloy into <u>CARBON CRUCIBLE</u>
4 Put <u>CARBON CRUCIBLE</u> into the muffle
Press
5 Machine will beep (<u>HOLD TIME</u> illuminates)
Press
6 Put your burned-out casting ring on the muffle
7 Close the chamber lid and move the locking arm down to the bottom
Chamber will invert then revert automatically
8 Done

Open the chamber lid